SENSOR WIRING



Wiring

NOTE: This unit is UL Listed and should be connected to a listed control unit or power supply providing at least 4 hours of standby power.



Contacts shown with power applied and no alarm